

1. PRIMARY CRASH ALARM AIR/GROUND INFORMATION

CALL 911 AND RELAY THE FOLLOWING AVAILABLE INFORMATION

A. Person Reporting Incident to You: (Include Name and Phone #)

John Hollingsworth

(913) 206-2921

B. Time incident Reported

06:49

C. Has a 911 Call Been Made?

N/A

D. Time Incident Occurred

06:40

E. Location of Accident

Mule DZ

MO

United States

F. Accident Site Accessibility

- Non Tactical Vehicle

G. Brief Description of Accident

****EXERCISE**** While conducting an ATM flight ACFT experienced a combining transmission chip detector caution. Aircrew executed a precautionary landing to Mule DZ, and initiated the pre-accident plan

H. Number and Severity of Injuries

0

I. Aircraft/ Vehicle type(s) and Tail/ Bumper Number(s)

12-08885

1. PRIMARY CRASH ALARM AIR/GROUND INFORMATION

CALL 911 AND RELAY THE FOLLOWING AVAILABLE INFORMATION

J. Damage to Aircraft/ Vehicle(s)

None

K. Crew/ Driver Name(s)

Edward Lambert, Jacob Meyers, Brett Hopkins

M. Is/was there a Fire

- No

N. Has a Fuel Spill been detected

- No
- N/A

O. Are there any Arms, Ammunition, or Explosives (AA&E) on Vehicles

- No
- N/A

P. Has Anyone Else Been Notified

- Yes

If yes please list

****EXERCISE****Primary crash alarm not needed. The chain of command and major players per the secondary alarm system were notified at approximately 0650(L).

Q. Is Anyone Already on the Incident Site

- No

R. Your Name, Time, Date

DAC John Hollingsworth

Time

1. PRIMARY CRASH ALARM AIR/GROUND INFORMATION

CALL 911 AND RELAY THE FOLLOWING AVAILABLE
INFORMATION

08:30

Date

10-03-2021