

APRIL 14, 2021



### Playgro Recalls Infant Activity Rattles Due to Choking Hazard

The abacus ring on the horses back can dislodge and release the small beads, posing a choking hazard to small children.

**Remedy:**

Consumers should immediately take the recalled rattles away from children, stop using them and contact Playgro for a free replacement, including shipping.

**Units:**

About 18,000

Consumer Contact:

**Website:**

<https://us.playgro.com/>

**E-mail:**

[customercare@playgro.com](mailto:customercare@playgro.com)

**Phone:** (855) 775-2947

APRIL 14, 2021



### Target Recalls Cat & Jack Baby Rompers Due to Choking Hazard

The heart-shaped graphics located on the knees of the romper can peel off or detach, posing a choking hazard to children.

**Remedy:**

Consumers should immediately take the recalled rompers away from children and return them to any Target Store for a full refund.

Consumers who purchased the romper on Target.com can contact Target to receive a prepaid return label to return the romper.

**Units:**

About 44,350

Consumer Contact:

**Website:**

<http://www.target.com/>

**Phone:** (800) 440-0680

APRIL 14, 2021



### Audio-Technica Recalls Charging Cases Sold with Wireless Headphones Due to Fire Hazard

The portable charging cases can overheat, posing a fire hazard.

**Remedy:**

Consumers should immediately stop using the charging cases and contact Audio-Technica for instructions on returning the charging cases for a free replacement charging case. Audio-Technica will provide consumers with a prepaid return shipping label and will send consumers a replacement charging case upon receipt of the returned case.

**Units:**

About 7,450

Consumer Contact:

**E-mail:**

[recall@atus.com](mailto:recall@atus.com)

**Phone:** (800) 518-2520

APRIL 14, 2021



**Battat Recalls Infant Teethers Due to Choking Hazard; Sold Exclusively at Target**

The plastic wings can detach from the body of the teether, posing a choking hazard to young children.

**Remedy:**

Consumers should immediately take the recalled teethers away from young children and return them to any Target store for a full refund, or contact Battat to return by mail for a full refund.

**Units:**

About 61,000 (In addition, about 210 were sold in Canada)

Consumer Contact:

**Website:**

<http://www.battatco.com>

**E-mail:**

[recalls@battatco.com](mailto:recalls@battatco.com)

**Phone:** (844) 963-2479

APRIL 12, 2021



**Black Diamond Recalls PIEPS DSP Avalanche Transceivers Due to Risk of Loss of Emergency Communications; One Death Reported**

The transceiver can switch modes unexpectedly when not locked or installed in the harness. When this occurs, it will prevent the transceiver from transmitting a signal and can make it difficult to locate a skier in an avalanche, which can result in severe bodily harm or death.

**Remedy:**

Consumers should immediately stop using the recalled avalanche transceivers and contact Black Diamond for a free replacement hardcase carrying system and user guide to be used with the recalled transceivers.

**Units:**

About 66,100 (In addition, about 12,500 were sold in Canada)

Consumer Contact:

**Website:**

<http://www.blackdiamondequipment.com>

**E-mail:**

[dsprecall@bdel.com](mailto:dsprecall@bdel.com)

**Phone:** (866) 306-0865



**Verizon Recalls 2.5 Million Ellipsis Jetpack Mobile Hotspots Imported by Franklin Wireless Due to Fire and Burn Hazards**

The lithium ion battery in the hotspots can overheat, posing fire and burn hazards.

**Remedy:**

Consumers can reduce the risk of hazard by powering the unit off, unplugging it from its power source and store in a place away from children, on top a hard surface with adequate ventilation around the unit and away from combustibles until it can be properly returned to Verizon.

If consumers must use the product for internet access, then they should take the following steps:

Turn the recalled hotspot "on" and plug it in to allow the hotspot to receive two over-the-air automatic software updates that:

- (a) enable the device's identifying number to be viewed on its scrolling screen and
- (b) prevent the device from charging while the device is plugged in and powered on.

After the software update is applied, users should:

- (a) Leave the device powered on while it is plugged in.
- (b) When not in use, the device should be turned off, unplugged from its power source, and securely stored.

Consumers should use the contact information below to receive a replacement hotspot free of charge and a return envelope to return the Ellipsis to Verizon for safe disposal.

Schools that provided the recalled Ellipsis Jetpack to students have been contacted by Verizon with instructions on receiving replacement hotspots free of charge and mailing packages to return the recalled Ellipsis Jetpacks to Verizon for safe disposal.

Parents whose children received the recalled Ellipsis Jetpack from their schools should contact their school for instructions on how to receive a free replacement device and return their recalled Ellipsis Jetpacks.

**Units:**

About 2.5 million

APRIL 8, 2021



**Verizon Recalls 2.5 Million Ellipsis Jetpack Mobile Hotspots Imported by Franklin Wireless Due to Fire and Burn Hazards**

The lithium ion battery in the hotspots can overheat, posing fire and burn hazards.

**Remedy:**

Consumers can reduce the risk of hazard by powering the unit off, unplugging it from its power source and store in a place away from children, on top a hard surface with adequate ventilation around the unit and away from combustibles until it can be properly returned to Verizon.

If consumers must use the product for internet access, then they should take the following steps:

Turn the recalled hotspot "on" and plug it in to allow the hotspot to receive two over-the-air automatic software updates that:

- (a) enable the device's identifying number to be viewed on its scrolling screen and
- (b) prevent the device from charging while the device is plugged in and powered on.

After the software update is applied, users should:

- (a) Leave the device powered on while it is plugged in.
- (b) When not in use, the device should be turned off, unplugged from its power source, and securely stored.

Consumers should use the contact information below to receive a replacement hotspot free of charge and a return envelope to return the Ellipsis to Verizon for safe disposal.

Schools that provided the recalled Ellipsis Jetpack to students have been contacted by Verizon with instructions on receiving replacement hotspots free of charge and mailing packages to return the recalled Ellipsis Jetpacks to Verizon for safe disposal.

Parents whose children received the recalled Ellipsis Jetpack from their schools should contact their school for instructions on how to receive a free replacement device and return their recalled Ellipsis Jetpacks.

**Units:**

About 2.5 million

APRIL 8, 2021



**GEO Essential Recalls Wintergreen Organic Essential Oil and Alleviate Organic Essential Oil Blend Due to Failure to Meet Child Resistant Packaging Requirement; Risk of Poisoning (Recall Alert)**

These products contain the substance methyl salicylate, which must be in child resistant packaging, as required by the Poison Prevention Packaging Act (PPPA). The packaging of the products is not child resistant, posing a risk of poisoning if the contents are swallowed by young children.

**Remedy:**

Consumers should immediately stop using the recalled essential oils and dispose of the products. Geo Essential is automatically refunding consumers the full purchase price through the distribution channel through which the products were purchased. GEO is contacting all known purchasers directly.

**Units:**

About 220

APRIL 7, 2021



### One Million Greenworks and Powerworks Pressure Washer Spray Guns Recalled Due to Impact Injury Hazard; Distributed by Hongkong Sun Rise Trading

The spray gun connector can break, causing the hose and/or parts of the connector to become dislodged during use, posing an impact injury hazard to the user.

**Remedy:**

Consumers should immediately stop using the recalled spray guns and contact Hongkong Sun Rise Trading for a free replacement of the spray gun handle.

**Units:**

About 1.06 million

APRIL 7, 2021



### Goal Zero Recalls Power Cables Due to Fire Hazard

The pins inside the connector on the power cord can deform and overheat, posing a fire hazard.

**Remedy:**

Consumers should immediately stop using the recalled cables and contact Goal Zero for a free replacement.

**Units:**

About 7,850

APRIL 7, 2021



### Epicure Recalls Glass Prep Bowls Due to Laceration Hazard

The tempered glass bowl can break or shatter during use, posing a laceration hazard.

**Remedy:**

Consumers should immediately stop using the recalled prep bowls and contact Epicure for a free replacement product.

**Units:**

About 1,600 (In addition, about 5,250 units were sold in Canada)

APRIL 7, 2021



### **RH Recalls Children's Bath Wraps Due to Violation of Federal Flammability Standard**

The recalled bath wraps fail to meet flammability standards for children's sleepwear, posing a risk of burn injuries to children.

#### **Remedy:**

Consumers should stop using the recalled bath wraps and contact RH for a full refund of the purchase price, or credit of \$35 for the Animal Bath Wrap, \$32 for the Heathered Bath Wrap or \$39 for the Sherpa Bath Wrap, if the consumer's purchase price cannot be determined. RH is contacting all known purchasers directly.

#### **Units:**

About 55,700 (In addition, about 3,900 units were sold in Canada)

APRIL 1, 2021



### **Infant Bath Seats Recalled Due to Drowning Hazard; Imported by BATTOP; Sold Exclusively on Amazon.com (Recall Alert)**

The bath seats fail to meet the federal safety standard for infant bath seats, including requirements for stability, and can tip over while in use, posing a drowning hazard to babies.

#### **Remedy:**

Consumers should immediately stop using the recalled infant bath seats and contact BATTOP for instructions on returning the bath seats with free shipping to receive a full refund. Amazon, on behalf of BATTOP, is contacting all known purchasers directly.

#### **Units:**

About 5,000

APRIL 1, 2021



### **dōTERRA Recalls 1.3 Million Bottles of Deep Blue, PastTense, and Deep Blue Touch Essential Oils Due to Failure to Meet Child Resistant Packaging Requirement; Risk of Poisoning (Recall Alert)**

The products contain the substance methyl salicylate, which must be in child resistant packaging as required by the Poison Prevention Packaging Act (PPPA). The packaging of the products is not child resistant, posing a risk of poisoning if the contents are applied to the skin or swallowed by young children.

#### **Remedy:**

Consumers should immediately store the products in a safe location out of reach of children and contact dōTERRA for a free replacement product of similar value. dōTERRA is contacting all known purchasers directly.

#### **Units:**

About 1.3 million

MARCH 25, 2021



**KTM, Husqvarna and GASGAS Recall Closed Course Competition Motorcycles Due to Crash Hazard (Recall Alert)**

The drive chain can break, posing a crash hazard and/or property damage.

**Remedy:**

Consumers should immediately stop riding the recalled closed course competition motorcycles and contact an authorized KTM, Husqvarna or GASGAS Motorcycles dealer to schedule a free repair, which involves replacing the drive chain. KTM, Husqvarna and GASGAS Motorcycles are contacting all purchasers directly.

**Units:**

About 1,470

MARCH 25, 2021



**Polaris Recalls Ranger Recreational Off-Highway Vehicles and ProXD, Gravelly and Bobcat Utility Vehicles Due to Fire Hazard (Recall Alert)**

The drive belt can break during operation and damage the inner clutch cover assembly and fuel line, which can result in a fuel leak, posing a fire hazard.

**Remedy:**

Consumers should immediately stop using the recalled vehicles and contact a Polaris, Ariens, or Bobcat dealer to schedule a free inspection and repair, if needed. Polaris, Ariens, and Bobcat are notifying all dealers and contacting registered owners directly.

**Units:**

About 41,500 (In addition, 1,475 units were sold in Canada) (some of the Model Year 2020-2021 RANGER 1000 and RANGER CREW 1000 and Model Year 2020 ProXD 2000G and ProXD 4000G units were previously recalled and some of the Model Year 2020 RANGER 1000 units were previously recalled for different hazards).

MARCH 25, 2021



**Inyo Pool Products Recalls PureLine Pool Pump Motors Due to Fire Hazard; Sold Exclusively on inyopools.com (Recall Alert)**

The pool pump motors can overheat, posing a fire hazard.

**Remedy:**

Consumers should immediately stop using the recalled pool pump motors and contact Inyo Pool Products for a free replacement. After replacement, consumers should cut one of the wires connecting to the capacitor and dispose of the recalled pump motors in accordance with local requirements. Consumers are asked to send a photo of the cut wires to Inyo Pool Products at [recall@inyopools.com](mailto:recall@inyopools.com). Inyo Pool Products is contacting all known purchasers directly.

**Units:**

About 800

MARCH 24, 2021



### **Birdie Belay Devices Recalled Due to Risk of Injury; Made by Beal Sas**

The device user can be unable to lower the climber, posing a risk of injury to the climber.

**Remedy:**

Consumers should immediately stop using the recalled Beal Birdie Belay Devices and contact Liberty Mountain for a free replacement.

**Units:**

About 1,400

MARCH 24, 2021



### **Flame King Recalls Hog 100-Pound Propane Cylinders Due to Fire Hazard**

The propane cylinders manufactured with a handle below the weld on the side could leak propane gas, posing a fire hazard.

**Remedy:**

Consumers should immediately stop using the recalled propane cylinders and contact Flame King for a full refund or free replacement.

**Units:**

About 500

MARCH 18, 2021



### **Briggs & Stratton Recalls YTL Log Splitters with Briggs & Stratton Engines Due to Injury Hazard (Recall Alert)**

An incorrect engine ignition coil and flywheel can lead to hard starting and engine kick back, posing an injury hazard to the operator.

#### **Remedy:**

Consumers should immediately stop using the recalled log splitters and contact an authorized Briggs & Stratton dealer for a free inspection and repair. Briggs & Stratton is contacting all purchasers directly.

#### **Units:**

About 9,750 (In addition, 290 were sold in Canada)

MARCH 18, 2021



### **HD Hudson Recalls Battery-Powered Sprayers Due to Fire Hazard**

The sprayer's lithium-ion battery can overheat, posing a fire hazard.

#### **Remedy:**

Consumers should immediately stop using the recalled battery-powered sprayers, remove the battery tray, and look for a brown battery. If the battery is brown, consumers should remove the battery and tray and dispose of them in accordance with local laws for disposal of lithium-ion batteries, and contact HD Hudson for a free replacement battery and tray. Always follow proper battery use and storage procedures as listed in the instructions.

#### **Units:**

About 64,000

MARCH 18, 2021



### **Genentech Recalls Prescription Drug Evrysdi Due to Failure to Meet Child Resistant Packaging Requirements; Risk of Drug Exposure through Eye or Skin Absorption (Recall Alert)**

The bottles containing the prescription drug can leak due to a fit issue between the press-in bottle adapter and bottleneck. If the bottle is leaking, there is a risk of drug exposure by contact with skin or eyes.

Prescription drugs must be in child resistant packaging that prevents children from gaining access to the contents as required by the Poison Prevention Packaging Act (PPPA).

#### **Remedy:**

Consumers should immediately store Evrysdi in a safe location out of reach and sight of children. Consumers should inspect the bottle for any leaking. If it is leaking, contact Genentech for a free replacement.

Consumers can continue to use as directed, as the leakage is not anticipated to impact the safety or efficacy of administered medicine. If Evrysdi gets on your skin, wash the area with soap and water. If Evrysdi gets in your eyes, rinse your eyes with water. Genentech is contacting all known purchasers directly.

#### **Units:**

About 14,000

MARCH 18, 2021



**Parker Squared Recalls Shepherd Boy Plush Toys with Wire Shepherd's Staff Due to Laceration Hazard (Recall Alert)**

The metal wire in the shepherd's staff can become exposed, posing a laceration hazard.

**Remedy:**

Consumers should immediately discard the toy's wire staff and contact The Shepherd's Treasure for a full refund of the value of the Shepherd Boy Plush Toy in the form of a gift certificate. Consumers can continue to use the plush toy without the shepherd's staff. The Shepherd's Treasure is contacting all purchasers directly.

**Units:**

About 3,000 (In addition, about 10 were sold in Canada)

MARCH 17, 2021



**HOFISH Recalls Mattresses Due to Violation of Federal Flammability Standard; Sold Exclusively on Amazon.com**

The mattresses fail to meet the mandatory federal flammability standard for mattresses, posing a fire hazard.

**Remedy:**

Consumers should immediately stop using the recalled mattresses and contact HOFISH to receive a free fitted cover to put on the mattress to bring it into compliance with the federal standard.

**Units:**

About 700

MARCH 17, 2021



**Global Home Imports Recalls Platform Bed Frames Due to Serious Injury Hazard**

The HR platform frame can collapse, posing a crush hazard that can result in severe injury or death.

**Remedy:**

Consumers should immediately stop using the recalled HR Platform Frames and contact Global Home Imports to receive a free repair kit with metal clips to strengthen the frame. Global Home Imports will ship a kit directly to consumers free of charge.

**Units:**

About 82,000

MARCH 11, 2021



**KTM and Husqvarna Motorcycles Recall Closed Course Competition Motorcycles Due to Crash Hazard (Recall Alert)**

Water can get into the battery causing a short circuit, posing a crash hazard.

**Remedy:**

Consumers should immediately stop riding the recalled motorcycles and contact an authorized KTM or Husqvarna Motorcycles dealer, respective of their motorcycle brand, to schedule a free repair. KTM and Husqvarna Motorcycles are contacting all known purchasers directly.

**Units:**

About 300

---

MARCH 11, 2021



**Melaleuca Recalls Three-Wick Revive Candles Due to Fire and Burn Hazards (Recall Alert)**

The candles' high flames can ignite the surface of the wax, posing fire and burn hazards.

**Remedy:**

Consumers should immediately stop using the recalled candles, carefully cut all three wicks as short as possible to prevent the candles from being used and discard the product. Melaleuca has contacted all known purchasers directly about the recall and refund.

**Units:**

About 38,000

MARCH 10, 2021



### **Hillsdale Furniture Recalls Jennings Counter and Bar Stools Due to Fall Hazard**

The stool seat can break off the base, posing a fall hazard.


**Remedy:**

Consumers should immediately stop using the recalled Jennings counter and bar stools and contact Hillsdale Furniture for a free repair kit.

**Units:**

About 10,570

MARCH 10, 2021



### **Lifetime Products Recalls 6-Foot Seminar Tables Due to Injury Risk**

The brace arms can fail to lock the table legs into place and the table can collapse, posing an injury risk to consumers.

**Remedy:**

Consumers should immediately stop using the recalled seminar tables and contact Lifetime Products for a free repair bracket.

**Units:**

About 43,000

MARCH 4, 2021



**Casa Kids Recalls for Repair Cabina Bunk Beds Due to Fall Hazard (Recall Alert)**

The screws that hold the bed's mattress foundation to the bed's guardrails can be loose and the mattress foundation can fall, posing a fall risk to children in the bunk bed.

**Remedy:**

Consumers should immediately stop using their recalled Cabina Bunk Beds until they have inspected their beds to determine whether the screws that hold the bed's foundation to the guardrails are tightly in place. Casa Kids is contacting all purchasers directly with detailed instructions on how to inspect and repair their bunk beds. Casa Kids will immediately send a new set of screws to any consumers who alert Casa Kids that their bed's guardrails are not tightly in place.

**Units:**

About 195

MARCH 4, 2021



**Polaris Recalls Ranger Recreational Off-Highway Vehicles and ProXD Utility Vehicles Due to Crash Hazard (Recall Alert)**

The throttle pedal can return to the idle position more slowly than anticipated once the pedal is released or stick in the depressed position, posing a crash hazard.


**Remedy:**

Consumers should immediately stop using the recalled vehicles and contact a Polaris dealer to schedule a free repair. Polaris is notifying all dealers and contacting registered owners directly.

**Units:**

About 15,800 (In addition, 711 units were sold in Canada)

MARCH 3, 2021



### Haro Bicycles Recalls Masi Evoluzione and Gran Corsa Bicycles Due to Fall Hazard and Risk of Injury

The bicycle's fork steerer tube can break, causing the rider to lose control, fall and suffer injuries.

**Remedy:**

Consumers should immediately stop using the recalled bicycles and contact their local Haro Bicycles dealer for a free inspection, and repair or replacement of the fork and compression plug.

**Units:**

About 510

FEBRUARY 25, 2021



### Dr. Reddy's Recalls Prescription Drug Blister Packages Due to Risk of Poisoning

The products are prescription medications that were labeled and distributed by Dr. Reddy's for institutional use only. The prescription medications were distributed by third party wholesalers to retail pharmacies and could have been dispensed to consumers. The packaging of the products is not child resistant and can pose a risk of poisoning if the contents are swallowed by young children.

**Remedy:**

Consumers should immediately store the recalled medications in a safe location out of reach of children and contact Dr. Reddy's for a full refund.

**Units:**

About 21,400